

INSPECTION REPORT					
OWNER	SELLER COMPANY			File nr	XXX
ADDRESS	XXX			INSP NUMBER	XXX
POSTAL CODE	XXX	CITY	XXX	STOCK NR	XXX
INSPECTION DATE	01/01/2020				

VEHICLE DETAILS			
Registration country	Netherlands	Engine (kw) / (hp)	316 kw / 430 pk
Brand	DAF	Emission class	Euro 4
Chassis nr	XXX	Gross weight (kg)	6725 kg
Model	85 CF	Gearbox type	Manual
Type	430	Suspension front/rear	leaf/air
Production year	26/06/2005	Color Exterior	White
Odo Meter read out (km)	867000	Number of passenger seats	2
Ignition keys	2	Color seats	Blue

TYRES			Profile depth (in mm)	
			Left	Right
Axle nr	Brand	Size	Outer / Inner	Outer / Inner
Front	Michelin	295 x 80 x R 22,5	4	4
Rear 1		295 x 80 x R 22,5	6/8	7/7
Rear 2				
Rear 3				
Rear 4				
Spare				

Tyre type	Summer	Winter	Original	Cover	Re-profile	Type / remarks
Front	x		x			energy XZA 2
Rear 1	x				x	energy XZA 2
Rear 2						
Rear 3						
Rear 4						
Spare						

Truck details					
Extra's accessoires					
PTO/ Hydrauliek/ Compressor	x	Double glass windows			Clang connection
Navigation system		Parking heater			Rema connection
DVD system		Cooling drawer / fridge			Microwave
Adaptive cruise control		Jack / Board tool			Lettering stuck
Lane departure warning		Air horn(s)			Signing painted
Xenon headlights		Spotlights in sun visor			ADR/VLG bord
LED headlights		Reading lights			27 MC
Headlight washer	x	Spotlights / fog lights bumper		x	220V inverter
Retarder/Intarder	x/x	Seats fabric			Sockets 220V
Steel rims		ABS and lighting cable			Window screen set
Alloy rims		Adjustable chairs			Tank protectors
Double bed		Air suspension passenger seat		x	
Leather driver seat		Hydraulic tailgate			

Inspection remarks	
additional information such as:	
* Visual check for leaks	
* Checking the functioning of instruments in the cabin	
* Checking the functionality of the accessories	

Note: This inspection is a visual inspection only. This inspection can't be seen as a technical inspection and can therefore not be interpreted as such. The inspection was performed without dismantling or removing parts, without performing a testdrive, without load on hydraulic and electrical installations and load on engine components, without activating liquid pumps and heating installations of tank trailers, without internal inspections of tank trailers and without setting up mobile tools. Therefore Truck-Time.com and possible sub contractors can not be held liable for matters that would not be visible by a plain visual test. The inspection is a snapshot of the state of the vehicle is currently in. Third parties can not derive any rights from this report without prior written permission from Truck-Time.com and possible sub contractors.

**INSPECTION REPORT**

Found defects / remarks interior

Part	Description	rep Method*	Photo No.
Footrest	missing (2 x pieces)	C	1&2
Table backrest	broken (2 x pieces)	C	3&4
Seat Upholstery	wear/damaged	C	5
Cover plate left front	Loose, fixed with tape and screw	R	6
Floor panel above 2e axle	Floor panel (wood) unstable/cracked approx 2 meters	C	7
Hinges refrigerator front	Broken, fixed with bolts through top cover	C	8
Driver dashboard	Damages on left side	R	9
Steering wheel	Upholstery loose	R	10

\* Legend: C Change R Repair CP Change and paint RP Repair and paint P Paint CI Cleaned P Polish Re Remove I Inspection needed

Note: This inspection is a visual inspection only. This inspection can't be seen as a technical inspection and can therefore not be interpreted as such. The inspection was performed without dismantling or removing parts, without performing a testdrive, without load on hydraulic and electrical installations and load on engine components, without activating liquid pumps and heating installations of tank trailers, without internal inspections of tank trailers and without setting up mobile tools. Therefore Truck-Time.com and possible sub contractors can not be held liable for matters that would not be visible by a plain visual test. The inspection is a snapshot of the state of the vehicle is currently in. Third parties can not derive any rights from this report without prior written permission from Truck-Time.com and possible sub contractors.

INSPECTION REPORT
-------------------

Found defects / remarks interior

Part	Description	rep Method*	Photo No.
Engine compart. Bottom	right side panel bent/deformed	R	1
Air spring bellows, rear axle re	left and right air leakage	C	2&3
Front protectors	left and right bent/deformed	R	4&5
Light covers luggage comp.	broken, repaired with tape (2x pieces)	C	6&7
Baseplate behind 2e axle	right side, bottom and side panel deformed	R	8&10
Mirror adjustment left	not working, electrical fault	R	11
Front bumper panel left	cracked and paint damage	CP	12& 13

\* Legend: C Change R Repair CP Change and paint RP Repair and paint P Paint CI Cleaned P Polish Re Remove I Inspection needed

Note: This inspection is a visual inspection only. This inspection can't be seen as a technical inspection and can therefore not be interpreted as such. The inspection was performed without dismantling or removing parts, without performing a testdrive, without load on hydraulic and electrical installations and load on engine components, without activating liquid pumps and heating installations of tank trailers, without internal inspections of tank trailers and without setting up mobile tools. Therefore Truck-Time.com and possible sub contractors can not be held liable for matters that would not be visible by a plain visual test. The inspection is a snapshot of the state of the vehicle is currently in. Third parties can not derive any rights from this report without prior written permission from Truck-Time.com and possible sub contractors.